

LARAMIE ENERGY LLC, Horseshoe Canyon Federal/1-33 Pad

Location # 312514



Wellhead – Photo #03131

Separator – Photo #03135

LARAMIE ENERGY LLC, Horseshoe Canyon Federal/1-33 Pad

Location # 312514



Tank Battery – Photo #03136



NE Corner of Location – Photo #03127

LARAMIE ENERGY LLC, Horseshoe Canyon Federal/1-33 Pad

Location # 312514



NW Corner of Location – Photo #03128

SW Corner of Location – Photo #03129

LARAMIE ENERGY LLC, Horseshoe Canyon Federal/1-33 Pad

Location # 312514



SE Corner of Location – Photo #03130



Location Lacks Stabilization – Photo #03140

LARAMIE ENERGY LLC, Horseshoe Canyon Federal/1-33 Pad

Location # 312514



Location Lacks Stabilization – Photo #03144

Location Lacks Stabilization – Photo #03141

LARAMIE ENERGY LLC, Horseshoe Canyon Federal/1-33 Pad

Location # 312514



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03145

Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03146

LARAMIE ENERGY LLC, Horseshoe Canyon Federal/1-33 Pad

Location # 312514



**Lease Road Degradation/Transport of Sediment –
Photo #03148**



**Lease Road Degradation/Transport of Sediment –
Photo #03149**

LARAMIE ENERGY LLC, Horseshoe Canyon Federal/1-33 Pad

Location # 312514



Lease Road Erosion/Transport of Sediment – Photo #03152



Insufficient Check Dam BMP – Photo #03153

LARAMIE ENERGY LLC, Horseshoe Canyon Federal/1-33 Pad

Location # 312514



**Insufficient Vehicle Tracking BMPs at Lease Road
Entrance/Exit – Photo #03158**