

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 7399 From entrance to location



Photo # 7400 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 7401 Location



Photo # 7402 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 4545 From Inspection 708900249 on 04/07/2023
Meter calibration info not conspicuously posted



Photo # 6913 From Inspection 708900405 on 05/04/2023
Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 7404 Meter calibration info not conspicuously posted



**Photo # 4546 From Inspection 708900249 on 04/07/2023
Meter calibration info not conspicuously posted**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 6914 From Inspection 708900405 on 05/04/2023
Meter calibration info not conspicuously posted



Photo # 7406 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 6921 From Inspection 708900405 conducted on 05/04/2023 Open cellar/wildlife hazard (Cellar is just off lease road approximately 25-50 yards past CLOUGH 2A pad)



Photo # 7409 Open cellar/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 6922 From Inspection 708900405 conducted on 05/04/2023 Open cellar/wildlife hazard (Cellar is just off lease road approximately 25-50 yards past CLOUGH 2A pad)



Photo # 7411 Open cellars/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 7414 Open cellars/wildlife hazard



Photo # 7415 Open cellars/wildlife hazard



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 7416 Open cellars/wildlife hazard



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources