


KPK  
Cody 1  
Location # 324594



location



location

KPK  
Cody 1  
Location # 324594




location




location



## Location # 324594



## location



### Battery lacking proper signage

KPK  
Cody 1  
Location # 324594



Weeds in secondary containment



Debris



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

KPK  
Cody 1  
Location # 324594



Debris



Valve on tank missing cap/plug

KPK  
Cody 1  
Location # 324594



Open thief hatch



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources