

KPK
Dwinell 3-A
Location # 324666



location



location signage and signage on the ground



KPK
Dwinell 3-A
Location # 324666



Weeds and cut slope lack of stabilization



Weeds



KPK
Dwinell 3-A
Location # 324666



Weeds



Debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

KPK
Dwinell 3-A
Location # 324666



Weeds



Cut slope shows signs of lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

KPK
Dwinell 3-A
Location # 324666



Cut slope shows signs of lack of stabilization



Debris