

Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298




Photo 1 – Wellhead – Unmarked Riser




Photo 2 – Gas Meter and Separator – Trash

Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298



Photo 3 – Tank Battery



Photo 4 – Trash and Debris

Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298



Photo 5 – Trash and Stained Soil



Photo 6 – Trash

Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298



Photo 7 – Trash



Photo 8 – Stained Soil

Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298



Photo 9 – Trash



Photo 10 – Unused Equipment to be moved to the outer edge on Location. (South End)

Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298



Photo 11 – Trash



Photo 12 – Unused Equipment to be moved to the outer edge on Location. (South End)

Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298



Photo 13 – Trash to be removed, useable pipe to be stored in a neat and orderly fashion



Photo 14 – Unused Equipment to be stored in a neat and orderly fashion

Inspection Photos
Location Name: Lost Creek 4
Location ID: 331298



Photo 15 – Trash to be removed, unused Equipment to be stored in a neat and orderly fashion




Photo 16 – Trash