

Inspection Photos
Location Name: Lost Creek 10
Location ID: 331757



Photo 1 – Water Tank – Labels missing



Photo 2 – Heater Treater House

Inspection Photos
Location Name: Lost Creek 10
Location ID: 331757



Photo 3 – Tank Battery

Photo 4 – Tank Labels

Inspection Photos
Location Name: Lost Creek 10
Location ID: 331757



Photo 5 – Unmarked Risers