

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage /GV 80-4

Location ID: 334813



Photo #9918 From entrance to location.



Photo #9919 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage /GV 80-4

Location ID: 334813



Photo #9920 From entrance to location.



Photo #9921 Calibration cards not conspicuously posted.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage /GV 80-4

Location ID: 334813



Photo #9922 Multiple places with Undesirable Plant Species



Photo #9923 Multiple places with Undesirable Plant Species

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage /GV 80-4

Location ID: 334813




Photo #9924 Loadline open ended.




Photo #9925 Loadline open ended.