

CAERUS PICEANCE LLC, ORCHARD UNIT-68S96W/17SWSW

Location #334147



NE Corner of Location – Photo #03277



SE Corner of Location – Photo #03278

CAERUS PICEANCE LLC, ORCHARD UNIT-68S96W/17SWSW

Location #334147



SW Corner of Location – Photo #03279



NW Corner of Location – Photo #03280

CAERUS PICEANCE LLC, ORCHARD UNIT-68S96W/17SWSW

Location #334147



Wellheads/Chemical Tank – Photo #03281



Separators – Photo #03283

CAERUS PICEANCE LLC, ORCHARD UNIT-68S96W/17SWSW

Location #334147



Tank Battery – Photo #03289

Location Lacks Stabilization – Photo #03288

CAERUS PICEANCE LLC, ORCHARD UNIT-68S96W/17SWSW

Location #334147



Location Lacks Stabilization – Photo #03292



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03294

CAERUS PICEANCE LLC, ORCHARD UNIT-68S96W/17SWSW

Location #334147



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #03293**