

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



Photo # 7873 From entrance to location



Photo # 7874 From entrance to location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



Photo # 7875 Location



Photo # 7876 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



Photo # 7877 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



Photo # 4508 From Inspection 708900244 conducted on 04/07/2023 Meter calibration info not conspicuously posted



Photo # 7878 Meter calibration info not conspicuously posted