

# Inspection Photos

ID: 150396

Operator: CHEMCO INC

Inspection Date: 5/15/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

ID: 150396 | Date: 5/15/2023

## Inspection Photos



**Photo 1.** Facing southeast toward the tank battery. Stained soils appear to be cleaned up at the west side of the tanks.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 5/15/2023

## Inspection Photos



**Photo 2.** There is still oil stained soil around the tank from a spill contained inside the bermed area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 5/15/2023



## Inspection Photos



**Photo 3.** There is still oil stained soil around the tank from a spill contained inside the bermed area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 5/15/2023

## Inspection Photos



**Photo 4.** The container at red arrow has been replaced to the pipe outlet.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 5/15/2023



## Inspection Photos



**Photo 5.** The electric line appears to have been buried to the tank battery. The line still hang by the pole and should be better protected with pipe, ect.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 5/15/2023

## Inspection Photos



**Photo 6.** There is still storage of pipe and equipment at the location. All equipment and supplies not necessary for use on this Oil and Gas Location is prohibited per Rule 606 and 1003.a.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 5/15/2023



## Inspection Photos



**Photo 7.** Facing northeast toward the storage shed which can remain.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 5/15/2023



## Inspection Photos



**Photo 8.** Most of the unused supplies stored in this area has been removed. The remainder including the work table should also be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 5/15/2023

## Inspection Photos



**Photo 9.** There is drilling pipe stored at the east side of the location that also needs to be removed. All supplies not necessary for use on the location is prohibited.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 5/15/2023



## Inspection Photos



**Photo 10.** Facing southwest at the tank battery location. All unused equipment not necessary for use on the location is prohibited and must be removed. All areas not necessary for operations need to be reclaimed per Rule 1003.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

ID: 150396 | Date: 5/15/2023

## Inspection Photos



**Photo 11.** Drone aerial imagery facing southwest toward the tank battery location. The location needs to be reduced in size through interim reclamation to be put back into cropland use. All unused equipment not necessary for use on the location is prohibited and must be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 5/15/2023