

Inspection Photos

May 16, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334592

Location Name: ROSE RANCH-67S93W/14NWSE

Inspection Document #: 702801521

Garfield County, CO

NWSE Section 14 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: ROSE RANCH-67S93W/14NWSE

Location ID: 334592



Photo 1. Photos show examples of list B noxious Scotch thistle on location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801521

Inspection Photos
Location Name: ROSE RANCH-67S93W/14NWSE
Location ID: 334592



Photo 2. Photo taken to the north shows the reclaimed access road.



Inspection Photos

Location Name: ROSE RANCH-67S93W/14NWSE

Location ID: 334592



Photo 3. Photos taken from the center show an overview to the north (left) and east (right) of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801521

Inspection Photos

Location Name: ROSE RANCH-67S93W/14NWSE

Location ID: 334592



Photo 4. Photos taken from the center show an overview to the south (left) and west (right) of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801521

Inspection Photos

Location Name: ROSE RANCH-67S93W/14NWSE

Location ID: 334592



Photo 5. Photo shows there does appear to be some young perennial grasses establishing in poorly vegetated areas.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801521

Inspection Photos

Location Name: ROSE RANCH-67S93W/14NWSE

Location ID: 334592



Photo 6. Photo shows an overview of the location. Poorly vegetated areas are primarily in the center/former working pad area. Former interim areas have better vegetation cover (foreground).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801521

Inspection Photos

Location Name: ROSE RANCH-67S93W/14NWSE

Location ID: 334592



Photo 7. Photos show reference areas to the east (left) and west (right).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801521