

# TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSW

## Location #323935



**NW Corner of Location – Photo #03481**



**SW Corner of Location – Photo #03482**

# TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSW

## Location #323935



**SE Corner of Location – Photo #03483**



**NE Corner of Location – Photo #03484**

# TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSW

Location #323935



Wellhead – Photo #03485

Separator – Photo #03488

# TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSW

Location #323935



Tank Battery – Photo #03490

Access Road Lacks Stabilization – Photo #03496

# TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSW

Location #323935



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03492**

**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03493**