

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324018



NW Corner of Location – Photo #03497



SW Corner of Location – Photo #03498

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324018




SE Corner of Location – Photo #03499




NE Corner of Location – Photo #03500

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324018



Wellhead – Photo #03501



Separator – Photo #03504



TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324018



Tank Battery – Photo #03507



Location Lacks Stabilization – Photo #03506

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324018



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #03509**