

Photo #1. View of leaking motor and impacted material.

Williford Dye Hard #8: Location ID/API #:067-07253



Photo #2. View of wellhead and scattered parts.

Williford Dye Hard #8: Location ID/API #:067-07253



Photo #3. View of crude oil tank and containment berm.