

Williford Dye Hard #1: Location ID/API #:067-05446



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo #1. Overview of well location, animal burrow in tank berm.

Williford Dye Hard #1: Location ID/API #:067-05446




Photo #2. View of flammable liquid storage near wellbore.

Williford Dye Hard #1: Location ID/API #:067-05446



Photo #3. View of inadequate tank integrity, leak.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources