

## Inspection Photos

Location Name: ROCKY MOUNTAIN LLC DIAMOND ELK-67S95W /12NWNW

Location ID: 334712



Photo #31 From entrance to location.



Photo #32 From entrance to location

## Inspection Photos

Location Name: ROCKY MOUNTAIN LLC DIAMOND ELK-67S95W /12NWNW

Location ID: 334712



Photo #33 From entrance to location.



Photo #36 Calibration cards not conspicuously posted.