


Stormwater Management and Erosion control

Location Name: CAERUS PICEANCE LLC BENTLEY-67S95W /11SWSE

Location #: 324168



Location Overview: Location is located in a high priority habitat area.

Section/Township/Range: 11 7S95W

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC BENTLEY-67S95W /11SWSE
Location #: 324168



Photo #40 Location lacks stabilization.



Photo #41 Location lacks stabilization.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC BENTLEY-67S95W /11SWSE
Location #: 324168



Photo #42 Insufficient tracking BMP at entrance to location to minimize the transport of sediment.