

Operator: Crestone Peak Resources

Location Name: GRENEMEYER WAGNER C UNIT-61N67W 34NWNW

Loc ID: 319014

Inspection: 709400134



Exhibit A

CA: Weeds and weed debris in the reclamation area around site. Operator failed to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606 to remove weed debris.

CA Resolution: Weeds and weed debris have been removed in compliance with Rule 606. (See Exhibit A)