

TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/36NWSW

Location #335253



SW Corner of Location – Photo #03638



SE Corner of Location – Photo #03639

TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/36NWSW

Location #335253



NE Corner of Location – Photo #03640



NW Corner of Location – Photo #03641

TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/36NWSW

Location #335253



Wellhead – Photo #03644



Separator – Photo #03646

TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/36NWSW

Location #335253



Tank Battery – Photo #03647



Location Lacks Stabilization – Photo #03650

TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/36NWSW

Location #335253



Location Lacks Stabilization – Photo #03651



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03654

TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/36NWSW

Location #335253



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #03653**