

Inspection Photos

5/19/2023

Operator: SCOUT ENERGY MANAGEMENT LLC
- 10779

Location Number: 397603
Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location Number: 397603



Photo 1: Photos 1-2 taken from the central areas of the Location facing north, east, south and west. Photos show areas of the Location that appear to be progressing towards 1004 reclamation standards; vegetation establishment beyond the drill rows will be necessary for establishment to be considered “uniform”.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location Number: 397603



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location Number: 397603



Photo 3: Photos taken from the east end of the Location. Photos examples showing areas of the Location where desirable vegetative establishment is not progressing towards 1004 standards.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location Number: 397603



Photo 4: Photo shows cable debris observed on the northeast end of the Location.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location Number: 397603




Photo 5: Photo shows utility pole equipment remaining on the Location.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location Number: 397603



Photo 6: Photo examples showing Undesirable Plant Species (halogeton) observed establishing on areas of the Location.