

Inspection Photos

May 17, 2023

Operator: POC-I LLC - #10386

Location ID: 312754

Location Name: ILES DOME UNIT-64N92W/23NWSW

Inspection Document #: 702801529

Moffat County, CO

NWSW Section 23 T4N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ILES DOME UNIT-64N92W/23NWSW
Location ID: 312754



Photo 1. Photo taken from the location entrance to the northwest shows an overview of the location. Note concrete slab, unstabilized cut slope and power line.



Inspection Photos

Location Name: ILES DOME UNIT-64N92W/23NWSW

Location ID: 312754



Photo 2. Photos show the location has not been recontoured, an unstabilized cut slope, and lack of vegetation establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801529

Inspection Photos

Location Name: ILES DOME UNIT-64N92W/23NWSW

Location ID: 312754



Photo 3. Photos show the location has not been recontoured and the cut slope is unstable. Vegetation is pedestaled with exposed roots. Erosion appears to be migrating upslope/backwards, undercutting into undisturbed reference areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801529

Inspection Photos
Location Name: ILES DOME UNIT-64N92W/23NWSW
Location ID: 312754



Photo 4. Photo shows erosion in the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801529

Inspection Photos

Location Name: ILES DOME UNIT-64N92W/23NWSW

Location ID: 312754



Photo 5. Photo taken from the east shows lack of vegetation establishment on the pad.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801529

Inspection Photos

Location Name: ILES DOME UNIT-64N92W/23NWSW

Location ID: 312754



Photo 6. Photos show equipment/debris associated with the location which must be removed.

Inspection Photos
Location Name: ILES DOME UNIT-64N92W/23NWSW
Location ID: 312754



Photo 7. Photos show equipment/debris on the access road. Debris is partially buried and on the surface.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801529

Inspection Photos

Location Name: ILES DOME UNIT-64N92W/23NWSW

Location ID: 312754



Photo 8. Photos show equipment/debris on the access road. Debris is partially buried and on the surface.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801529

Inspection Photos

Location Name: ILES DOME UNIT-64N92W/23NWSW

Location ID: 312754



Photo 9. Photo taken to the northeast show examples of equipment/debris from the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801529

Inspection Photos

Location Name: ILES DOME UNIT-64N92W/23NWSW

Location ID: 312754



Photo 10. Photos show rebar (left) and a cable (right). Debris associated with the location is widespread throughout the area and found both on and off location.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801529

Inspection Photos
Location Name: ILES DOME UNIT-64N92W/23NWSW
Location ID: 312754



Photo 11. Photos show examples of List B Noxious Weeds musk thistle (left), houndstongue (center) and whitetop (right) which are found occasionally throughout the location.

Inspection Photos
Location Name: ILES DOME UNIT-64N92W/23NWSW
Location ID: 312754



Photo 12. Photo taken from the northwest shows the start of the reclaimed access road.

Inspection Photos

Location Name: ILES DOME UNIT-64N92W/23NWSW

Location ID: 312754



Photo 13. Photo shows reference areas to the south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801529