

# TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWNE

## Location #324156



**SW Corner of Location – Photo #03672**



**NW Corner of Location – Photo #03673**

# TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWNE

## Location #324156



SE Corner of Location – Photo #03674

Wellhead – Photo #03675

# TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWNE

## Location #324156



Separator – Photo #03680



Tank Battery – Photo #03681

# TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWNE

## Location #324156



Location Lacks Stabilization – Photo #03677



Location Lacks Stabilization – Photo #03678

# TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWNE

## Location #324156



**Location Lacks Stabilization – Photo #03679**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03685**