

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 223-22 Pad

Location ID: 324058



Photo # 8257 From entrance to location



Photo # 8258 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 223-22 Pad

Location ID: 324058



Photo # 8259 Location



Photo # 8260 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 223-22 Pad

Location ID: 324058



Photo # 3592 From Inspection 708900185 conducted on 03/29/2023 Meter calibration info not conspicuously posted



Photo # 8264 Meter calibration info not conspicuously posted