

Interim Reclamation and Stormwater Inspection

Date: 05/17/2023

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 456563

Inspection Document #: 708200269

Weld County, CO

SWNW Section 8 T9N R59W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Timbro 9-59 8A
Location ID: 456563



Photo 1. Some desirable vegetation establishment observed throughout the interim areas, however, the reclaimed portions are predominantly undesirable vegetation (e.g. kochia) that will need to be managed. This location does not appear to be progressing towards Rule 1003 Standards.

Inspection Photos
Location Name: Timbro 9-59 8A
Location ID: 456563



Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: Timbro 9-59 8A
Location ID: 456563



Photo 3. See comments in Photo 1.

Inspection Photos
Location Name: Timbro 9-59 8A
Location ID: 456563



Photo 4. See comments in Photo 1.

Inspection Photos
Location Name: Timbro 9-59 8A
Location ID: 456563



Photo 5. See comments in Photo 1.

Inspection Photos
Location Name: Timbro 9-59 8A
Location ID: 456563



Photos 6 & 7. Stained soil observed on location will need to be properly disposed of per Rule 905.e.

Inspection Photos
Location Name: Timbro 9-59 8A
Location ID: 456563




Photo 8. Several areas of the production pad/stormwater berm have been compromised with evidence of sediment transport into the interim areas. Gully and rill erosion are evident in several locations and will need to be repaired to prevent further degradation to adjacent interim areas.

Inspection Photos
Location Name: Timbro 9-59 8A
Location ID: 456563



Photo 9. See comments in Photo 8.

Inspection Photos
Location Name: Timbro 9-59 8A
Location ID: 456563



Photo 10. Continued from Photo 9; see also comments in Photo 8.

Inspection Photos
Location Name: Timbro 9-59 8A
Location ID: 456563



Photo 11. Continued from Photo 10; see also comments in Photo 8.

Inspection Photos
Location Name: Timbro 9-59 8A
Location ID: 456563



Photo 12. See comments in Photo 8.

Inspection Photos
Location Name: Timbro 9-59 8A
Location ID: 456563



Photo 13. See comments in Photo 8.

Inspection Photos
Location Name: Timbro 9-59 8A
Location ID: 456563



Photo 14. See comments in Photo 8.

Inspection Photos
Location Name: Timbro 9-59 8A
Location ID: 456563




Photo 15. See comments in Photo 8.