

Inspection Photos

May 17, 2023

Operator: GRMR OIL & GAS LLC - #10524

Location ID: 418843

Location Name: Durham/1-31, 2-31

Inspection Document #: 702801537

Moffat County, CO

SWSE Section 31 T5N R90W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Durham/1-31, 2-31
Location ID: 418843



Photo 1. Photos show equipment remaining on location.



Inspection Photos
Location Name: Durham/1-31, 2-31
Location ID: 418843



Photo 2. Photo taken from the northeast shows an overview of the southern/fill portion of the location.



Inspection Photos
Location Name: Durham/1-31, 2-31
Location ID: 418843



Photo 3. Photo taken from the northeast shows an overview of the northern/cut portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801537

Inspection Photos
Location Name: Durham/1-31, 2-31
Location ID: 418843



Photo 4. Photo taken from the northeast shows an overview of the eastern/more recently expanded portion of the location.



Inspection Photos
Location Name: Durham/1-31, 2-31
Location ID: 418843



Photo 5. Photo shows the cut slope at the northwest of the location. The location has not been recontoured, slopes are bare, unvegetated and unstabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801537

Inspection Photos
Location Name: Durham/1-31, 2-31
Location ID: 418843



Photo 6. Photo shows the cut slope at the north of the location. The location has not been recontoured, slopes are bare, unvegetated and unstabilized.



Inspection Photos
Location Name: Durham/1-31, 2-31
Location ID: 418843



Photo 7. Photo show the cut slope at the north of the location. The location has not been recontoured, slopes are bare, unvegetated and unstabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801537

Inspection Photos
Location Name: Durham/1-31, 2-31
Location ID: 418843



Photo 8. Photo taken from the county road to the south shows an overview of the fill slopes. The location has not been recontoured, slopes are bare, unstabilized and unvegetated or colonized by undesirable plant species/weeds.



Inspection Photos
Location Name: Durham/1-31, 2-31
Location ID: 418843



Photo 9. Photo shows the pad surface, fill slopes and berms are colonized by noxious weeds (bull, musk thistle, houndstongue and cheatgrass) and undesirable plant species/weeds (Russian thistle).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801537

Inspection Photos
Location Name: Durham/1-31, 2-31
Location ID: 418843



Photo 10. Photo shows noxious weeds (bull and musk thistle) and undesirable plant species/weeds (Russian thistle).

