

Inspection Photos

May 17, 2023

Operator: GRMR OIL & GAS LLC - #10524

Location ID: 312930

Location Name: BEAVER-DURHAM-65N90W/32NWSW

Inspection Document #: 702801541

Moffat County, CO

NWSW Section 32 T5N R90W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: BEAVER-DURHAM-65N90W/32NWSW

Location ID: 312930



Photo 1. Photo taken from the southeast facing towards the location shows the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801541

Inspection Photos

Location Name: BEAVER-DURHAM-65N90W/32NWSW

Location ID: 312930



Photo 2. Photos taken from the center of the location show an overview to the north (left) and east (right). Note vegetation does not appear to be 80% of reference and presence of bare soil. Note also vegetation at the location center (in former working pad/equipment areas) is not as well established as at the edges of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801541

Inspection Photos

Location Name: BEAVER-DURHAM-65N90W/32NWSW

Location ID: 312930



Photo 3. Photos taken from the center of the location shows an overview to the south (left) and west (right). Note vegetation does not appear to be 80% of reference and presence of bare soil. Note also vegetation at the location center (in former working pad/equipment areas) is not as well established as at the edges of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801541

Inspection Photos

Location Name: BEAVER-DURHAM-65N90W/32NWSW

Location ID: 312930



Photo 4. Photo shows an examples of areas throughout the location where vegetation establishment is not uniform. Perennial species are not established, bare ground is common and occasional noxious weeds are colonizing bare spaces (circled).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801541

Inspection Photos

Location Name: BEAVER-DURHAM-65N90W/32NWSW

Location ID: 312930



Photo 5. Photos show examples of areas throughout the location where vegetation establishment is not uniform. Perennial species are not established, bare ground is common.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801541

Inspection Photos

Location Name: BEAVER-DURHAM-65N90W/32NWSW

Location ID: 312930



Photo 6. Photos show examples of areas throughout the location where vegetation establishment is not uniform. Perennial species are not established, bare ground is common.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801541

Inspection Photos

Location Name: BEAVER-DURHAM-65N90W/32NWSW

Location ID: 312930



Photo 7. Photo shows an example of a portion of the location with good perennial establishment that appears comparable to reference in terms of percent coverage of perennial species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801541

Inspection Photos

Location Name: BEAVER-DURHAM-65N90W/32NWSW

Location ID: 312930



Photo 8. Photos show reference areas to the north. Note dense coverage of perennial grasses, forbs and shrubs.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801541