

**Inspection Photos**  
**Location Name: Pyles 4**  
**API: 05-061-06182**



- 1. Oil stained dirt on south side of pumping unit needs removed**

**Insp #701007015 performed in accordance with Complaint Doc #403326304**