

LARAMIE ENERGY LLC, Jensen/19-01 Pad

Location #426451



SW Corner of Location – Photo #03810



SE Corner of Location – Photo #03811

LARAMIE ENERGY LLC, Jensen/19-01 Pad

Location #426451



NW Corner of Location – Photo #03812



NE Corner of Location – Photo #03813

LARAMIE ENERGY LLC, Jensen/19-01 Pad

Location #426451



Wellhead – Photo #03814



Separator – Photo #03817

LARAMIE ENERGY LLC, Jensen/19-01 Pad

Location #426451



Tank Battery – Photo #03820



Location Lacks Stabilization – Photo #03819

LARAMIE ENERGY LLC, Jensen/19-01 Pad

Location #426451



Location Lacks Stabilization – Photo #03821

Location Lacks Stabilization – Photo #03822

LARAMIE ENERGY LLC, Jensen/19-01 Pad

Location #426451



**Rill Erosion Transporting Sediment onto Location –
Photo #03823**



**Rill Erosion Transporting Sediment onto Location –
Photo #03824**

LARAMIE ENERGY LLC, Jensen/19-01 Pad

Location #426451



**Rill Erosion Transporting Sediment onto Location –
Photo #03825**



**Rill Erosion Transporting Sediment onto Location –
Photo #03828**

LARAMIE ENERGY LLC, Jensen/19-01 Pad

Location #426451



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03829



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03830