

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 33-32

Location ID: 413524



Photo # 8778 From entrance to Location



Photo # 8779 From entrance to Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 33-32

Location ID: 413524



Photo # 8781 Location



Photo # 8782 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 33-32

Location ID: 413524



Photo # 8783 Location



Photo # 2577 From Inspection 708900132 conducted on 03/20/2023 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 33-32

Location ID: 413524



Photo # 8784 Meter calibration info not conspicuously posted



Photo # 8785 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 33-32

Location ID: 413524



Photo # 8786 Meter calibration info not conspicuously posted



Photo # 8787 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 33-32

Location ID: 413524



Photo # 8791 Debris