

LARAMIE ENERGY LLC, BCU/14F Pad

Location #312374



SW Corner of Location – Photo #03901



SE Corner of Location – Photo #03902

LARAMIE ENERGY LLC, BCU/14F Pad

Location #312374



NE Corner of Location – Photo #03903



Wellhead – Photo #03904

LARAMIE ENERGY LLC, BCU/14F Pad

Location #312374



Separator – Photo #03906



Tank Battery – Photo #03907

LARAMIE ENERGY LLC, BCU/14F Pad

Location #312374



Location Lacks Stabilization – Photo #03909



Location Lacks Stabilization – Photo #03912

LARAMIE ENERGY LLC, BCU/14F Pad

Location #312374



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03913



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03914