

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2023

Submitted Date:

05/25/2023

Document Number:

696304941

**FIELD INSPECTION FORM**Loc ID 421212 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448673	TANK BATTERY	AC	12/12/2016		-	Fabrizius-Lari	AC

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	East 500 Crude Oil Tank - Capacity Label; see photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/26/2023
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Heater Treater	# 2		
Comment:	NFPA Labels peeled away; see photos		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	06/26/2023
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <a href="#">Shares berm with other Crude Oil Tanks</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <a href="#">Shares berm with Crude Oil Tanks</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		Shares berm with Crude Oil Tanks					
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	2	500 BBLs	STEEL AST		40.878300,-104.219300		
Comment:							
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
<b>Venting:</b>							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
<b>Flaring:</b>							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities									
Facility ID:	448673	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	AC
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: <input type="text" value="SI - Facility Shut-In at the time of this Inspection"/>									
Corrective Action: <input type="text"/> Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. NFPA Lables on Heater Treaters and Crude Oil Capacity Label</a>	petrie	05/25/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403413654	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6125751">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6125751</a>
696304942	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6125748">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6125748</a>