


Inspection Photos
Location Name: North Washington 1-23
Location ID: 336041



Photo#1 Production Tanks

Photo#2 Stained Soil on backside of furthest east production tank


Inspection Photos
Location Name: North Washington 1-23
Location ID: 336041



Photo#3 Produced Water Tanks/**No sign showing bbl amount**

Photo#4 Automation RTU/(2)Separators/(3)ECDs/Gas Meter

Inspection Photos
Location Name: North Washington 1-23
Location ID: 336041



Photo#5 Gas Meter not calibrated

Photo#6 North Washington 1-23 Wellhead

Inspection Photos
Location Name: North Washington 1-23
Location ID: 336041



Photo#7 Temp Tank