

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 33-22 pad

Location ID: 335367



Jun 2, 2023 at 10:50:21 AM  
CO



Jun 2, 2023 at 10:51:09 AM  
CO

Photo # 9198 From entrance to location

Photo # 9199 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 33-22 pad

Location ID: 335367



Photo # 9200 Location



Photo # 9201 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 33-22 pad

Location ID: 335367




Photo # 2750 From Inspection 708900140 conducted on 03/21/2023 Meter calibration info not conspicuously posted



Photo # 9212 Meter calibration info not conspicuously posted

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 33-22 pad

Location ID: 335367



**Photo # 9213 Meter calibration info not conspicuously posted**



**Photo # 9214 Meter calibration info not conspicuously posted**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 33-22 pad

Location ID: 335367



**Photo # 9215 Meter calibration info not conspicuously posted**