

**Robert L Bayless Producer LLC  
Deer Creek State 1 (16-4-91)  
Location #312953**



**Access road to location**



**Entrance to location**



**Robert L Bayless Producer LLC**  
**Deer Creek State 1 (16-4-91)**  
**Location #312953**



**Well sign**



**Tank battery sign**



**Robert L Bayless Producer LLC  
Deer Creek State 1 (16-4-91)  
Location #312953**



**Unmarked anchor**



**Debris**



**Robert L Bayless Producer LLC  
Deer Creek State 1 (16-4-91)  
Location #312953**



**Unlabeled tank**



**Unlabeled tank**



**Robert L Bayless Producer LLC  
Deer Creek State 1 (16-4-91)  
Location #312953**



**Pumping unit leak with stained soil**



**Engine leak(s) with stained soil**



**Robert L Bayless Producer LLC  
Deer Creek State 1 (16-4-91)  
Location #312953**



**Stained soil**



**Containment failure**



**Robert L Bayless Producer LLC  
Deer Creek State 1 (16-4-91)  
Location #312953**



**Open to wildlife**



**Erosion and sediment migration leaving location**



**Robert L Bayless Producer LLC  
Deer Creek State 1 (16-4-91)  
Location #312953**



**Location from Northeast corner**



**Location from Southeast corner**



**Robert L Bayless Producer LLC  
Deer Creek State 1 (16-4-91)  
Location #312953**



**Location from Southwest corner**



**Location from Northwest corner**