

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH-66S95W /33SESW

Location ID: 334877



Photo #247 From entrance to location.



Photo #248 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH-66S95W /33SESW

Location ID: 334877



Network: Jun 5, 2023 at 12:44:25 PM MDT
Local: Jun 5, 2023 at 12:44:25 PM MDT
N 39° 28' 40", W 108° 0' 23"
CO

Photo #250 Calibration cards not conspicuously posted.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources