

Inspection Photos
Location Name: FLADER INDUSTRIES #1
Location ID: 319864



Photo# 1 Crude tanks.



Photo# 2 Separator.

Inspection Photos
Location Name: FLADER INDUSTRIES #1
Location ID: 319864



Photo# 3 P/W tank.



Photo# 4 Stained soil on east side of P/W tank/

Inspection Photos
Location Name: FLADER INDUSTRIES #1
Location ID: 319864



Photo# 5 Pit. Weeds in pit.



Photo# 6 Pit. Weeds in pit.

Inspection Photos
Location Name: FLADER INDUSTRIES #1
Location ID: 319864



Photo# 7 Pump Jack.



Photo# 8 weeds and no secondary containment for chemical bbl.