

**Inspection Photos**  
**Location Name: LINNEBUR 2-R**  
**Location ID: 320305**



**Photo# 1 Tanks.**



**Photo# 2 stained soil around loadout bucket.**

Inspection Photos  
Location Name: LINNEBUR 2-R  
Location ID: 320305



**Photo# 3 Separator.**



**Photo# 4 Pit.**



Inspection Photos  
Location Name: LINNEBUR 2-R  
Location ID: 320305



**Photo# 5 Pump jack.**



**Photo# 6 no secondary containment for chemicals.**

