

Inspection Photos

May 30, 2023

Operator: TEP Rocky Mountain- #96850

Location ID: 452566

Location Name: FEDERAL/RU 23-17

Inspection Document #: 702801570

Garfield County, CO

NESW Section 17 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: FEDERAL/RU 23-17
Location ID: 452566



Photo 1. Photo taken from the south shows an overview of the Location. Note overall, interim areas are very well vegetated.



Inspection Photos
Location Name: FEDERAL/RU 23-17
Location ID: 452566



Photo 2. Photos show production areas and the lack of tank battery sign (center).



Inspection Photos
Location Name: FEDERAL/RU 23-17
Location ID: 452566



Photo 3. Photos show lack of stabilization of the working pad surface.



Inspection Photos
Location Name: FEDERAL/RU 23-17
Location ID: 452566



Photo 4. Photos show slumping in the interim area directly to west of the separators.



Inspection Photos
Location Name: FEDERAL/RU 23-17
Location ID: 452566



Photo 5. Photos show slumping in the southern interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801570

Inspection Photos
Location Name: FEDERAL/RU 23-17
Location ID: 452566



Photo 6. Photo shows slumping in the southern interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801570

Inspection Photos
Location Name: FEDERAL/RU 23-17
Location ID: 452566



Photo 7. Photos show a stormwater ditch to the south of the working pad. Stormwater is eroding the ditch and cutting beneath rock check dams degrading the BMPs and resulting in increased sediment loads.



Inspection Photos
Location Name: FEDERAL/RU 23-17
Location ID: 452566



Photo 8. Photos show sediment transport and offsite degradation from the sediment trap at the southeast.



Inspection Photos
Location Name: FEDERAL/RU 23-17
Location ID: 452566



Photo 9. Photo shows musk thistle, a List B Noxious Weed observed at the ditch and sediment trap in the eastern interim area. .



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801570