

Inspection Photos
Location Name: Booth 3-23
Location ID: 429799



Photo 1: Wellhead Sign




Photo 2: Stained soil removed

Inspection Photos
Location Name: Booth 3-23
Location ID: 429799



Photo 3: BBLs installed



Photo 4: BBLs installed

Inspection Photos
Location Name: Booth 3-23
Location ID: 429799



Photo 5: BBLs installed




Photo 6: Gas meter appears to be calibrated

Inspection Photos
Location Name: Booth 3-23
Location ID: 429799



Photo 7: No BBLS installed



Photo 8: No BBLS installed