

Inspection Photos

API: 055-06189

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/6/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the former access road. There is less weeds growing but vegetation is sparse along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/6/2023

Inspection Photos



Photo 2. Facing east toward the location. There is mostly bare ground at the location and a reduction in noxious weeds was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/6/2023

Inspection Photos



Photo 3. Facing west toward the location. There is mostly bare ground at the location and a reduction in noxious weeds was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/6/2023

Inspection Photos



Photo 4. Facing east toward the surrounding undisturbed reference area which consists of desirable vegetation Western wheat grass, Sand dropseed among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/6/2023