

Operator: 8 NORTH LLC

Location Name: Fabrizzius PC GK33-99HZ Tank

Loc ID: 421212

Inspection: 696304941



Exhibit A

CA: East 500 Crude Oil Tank - Capacity Label; Install sign to comply with Rule 605.h.

CA Resolution: Signage/Label on Oil Tank has been replaced with a new one to comply with Rule 605.h.



Exhibit A



Exhibit B

CA: NFPA Labels peeled away. Install sign to comply with Rule 605.g.

CA Resolution: New NFPA Labels have been installed to comply with 605.g.