

Operator: 8 NORTH LLC

Location Name: FABRIZIUS 33-14

Loc ID: 413933

Inspection: 696304950



Exhibit A



Exhibit B

CA: Stained Soil at Wellhead, Gas Engine, and Exhaust. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

CA Resolution: Identified stained soil at Wellhead, Gas Engine, and Exhaust has been properly addressed. Operator has disposed of stained soil and replaced it with fresh soil to comply with Rule 905.e.