

Inspection Photos
Location Name: Anschutz State 5-62-27-34 SESE 22 PAD
Location ID: 421665



Photo 1 – Tank Battery Signs



Photo 2 – Tank Battery

Inspection Photos
Location Name: Anschutz State 5-62-27-34 SESE 22 PAD
Location ID: 421665



Photo 3 – Production Equipment



Photo 4 – Treater House – Unmarked Riser

Inspection Photos
Location Name: Anschutz State 5-62-27-34 SESE 22 PAD
Location ID: 421665



Photo 5 – Unmarked Riser




Photo 6 – Unmarked Riser

Inspection Photos

Location Name: Anschutz State 5-62-27-34 SESE 22 PAD

Location ID: 421665



Photo 7 – Separators



Photo 8 – ECDs

Inspection Photos
Location Name: Anschutz State 5-62-27-34 SESE 22 PAD
Location ID: 421665




Photo 9 – Unmarked Riser



Photo 10 – Unmarked Risers

Inspection Photos

Location Name: Anschutz State 5-62-27-34 SESE 22 PAD

Location ID: 421665




Photo 11 – Unmarked Riser



Photo 12 – Stained Soil at Exhaust

Inspection Photos
Location Name: Anschutz State 5-62-27-34 SESE 22 PAD
Location ID: 421665




Photo 13 – Stained Soil



Photo 14 – Stained Soil

Inspection Photos

Location Name: Anschutz State 5-62-27-34 SESE 22 PAD

Location ID: 421665



Photo 15 – Unused Wellhead Parts



Photo 16 – Wellhead

Inspection Photos

Location Name: Anschutz State 5-62-27-34 SESE 22 PAD

Location ID: 421665



Photo 17 – Well Sign



Photo 18 – 4-22H Pumping Unit

Inspection Photos
Location Name: Anschutz State 5-62-27-34 SESE 22 PAD
Location ID: 421665



Photo 19 – 5-27-62-0857H Pumping Unit



Photo 20 – 5-27-62-0857H Wellhead Sign