

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2023

Submitted Date:

05/30/2023

Document Number:

700300597**FIELD INSPECTION FORM**Loc ID 451450 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES LLCAddress: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stevens, Glenn	970-749-0192	glennstevens@centurylink.net	<a href="#">SW Inspection Reports</a>
Williford, Hearne		hwilli@swbell.net	<a href="#">All SW field inspections</a>
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451450	LOCATION	AC	07/22/2017		-	West Combustor Facility	AC

**General Comment:**[Data collected on 5/18 and 5/25 2023.](#)[Variance ORDER NO. 1-265, The Commission granted permission for operator to produce and combust casing gas only until Jan 15, 2023](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Operator name, number and facility name would be appropriate at this facility

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment	# 1		
Comment:	solar panel/telemetry		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Meter running at time of inspection, no calibration record displayed		
Corrective Action:	Display calibration record per rule 430.d		Date: <u>06/30/2023</u>
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	OTHER	OTHER		,	
Comment:	Potentially dangerous condition to have full or empty condensate barrels near fired equipmet/combustor					
Corrective Action:	Remove tank from same containment berm as fired equipment, tanks must be at least 75' from fired equipment per Rule 608.a(5) and 602.c				Date:	<u>06/08/2023</u>

**Paint**

Condition	
Other (Content)	
Other (Capacity)	55 gal
Other (Type)	temporary sealed drip gas collection/storage tank

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	metal drum also in plastic spill prevention within berm for combustor. Unclear how tank is grounded to prevent static discharge				
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	Ignitor/Combustor	
Comment:	Variance ORDER NO. 1-265, The Commission granted permission for operator to produce and combust casing gas only until Jan 15, 2023	
Corrective Action:		Date:



**Optical Gas Imaging Survey**

Survey Type: \_\_\_\_\_

Current Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: \_\_\_\_\_ Speed: \_\_\_\_\_ (mph) Direction From: \_\_\_\_\_ Weather: \_\_\_\_\_ Temperature: (F) \_\_\_\_\_

Assisting Staff: \_\_\_\_\_ Camera #: \_\_\_\_\_

☐ Visible Smoke ☐ Referred to CDPHE

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403419705	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6132213">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6132213</a>
700300598	combustor, flowline, condensate drum	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6132181">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6132181</a>
700300599	gas meter, no calibration record	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6132182">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6132182</a>
700300600	20230518 FLIR	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6132183">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6132183</a>
700300601	20230525 FLIR	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6132184">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6132184</a>