



## Work Completion Report

### Completion Header

---

<b>Location Completed</b>	GRENNEMYER_35C-3HZ
<b>Alt Loc Name</b>	GRENNEMYER_35C-3HZ
<b>Visited On</b>	05/18/2023
<b>Performed By</b>	Northern Colorado Constructors (NCC)
<b>One-Call Number</b>	A313801708
<b>Red Zone Date</b>	5/25/2023 12:00:00 AM
<b>Red Zone APC Rep</b>	Drew Stormo

### Location Details

---

<b>Location</b>	GRENNEMYER_35C-3HZ
<b>Location Type</b>	Regulatory
<b>Land Use - Insp</b>	Pasture
<b>Crop Type</b>	
<b>Latitude/Longitude</b>	40.013615/-104.880377
<b>Legal Address</b>	(WELD) NENW 34 1N67W
<b>COGCC Loc ID</b>	434787
<b>Land Rep</b>	
<b>Road Directions</b>	CR 4 & CR 19, S. 0.07 MI, E/SE 0.25 MI INTO.
<b>Land Use - Loc</b>	Pasture
<b>Rec Contractor PO(s)</b>	NCC - 4501313284
<b>Vendor PO(s)</b>	GRANITE - 4501313347, WESTERN - 4501364170



## Work Completion Report



## Work Completion Report

### Work Completion Details

---

<b>Assoc Work Task</b>	Evaluate and complete interim reclamation practice
<b>Assoc Job</b>	GRENNEMYER 35C-3HZ, WAGNER 34N-34HZ
<b>Work Summary</b>	mow site. Repair ruts, rip, disk, drill seed, spread straw, and crimp. Overseed a few areas.
<b>SqFtAffected</b>	87120.00000
<b>AcresAffected</b>	2.00000
<b>Seed Mix</b>	Dryland Maintenance (36.39 lbs)
<b>LandUse</b>	Pasture
<b>CropType</b>	
<b>SoilType</b>	Clay Loam
<b>CompletionDate</b>	5/30/2023 12:00:00 AM
<b>StabilizationDate</b>	
<b>SeedingDate</b>	
<b>Mulch</b>	Straw at (No Rate)
<b>Straw Bales</b>	4 bales at 3 x 4 squares (Contractor-supplied)
<b>SoilAmendType</b>	none
<b>SoilAmendUnits</b>	
<b>SoilAmendAmount</b>	
<b>SoilAmendRate</b>	NA
<b>Top Soil</b>	NA
<b>Topsoil Source</b>	
<b>General Notes</b>	



## Work Completion Report

### Work Task Details

---

<b>Work Task</b>	Evaluate and complete interim reclamation practice
<b>Job</b>	GRENNEMYER 35C-3HZ, WAGNER 34N-34HZ
<b>Requested On</b>	5/2/2023 12:00:00 AM
<b>Requested By</b>	Tyler Scherden
<b>Did COGCC issue a CA for Work?</b>	No
<b>Start By Date</b>	
<b>Due By Date</b>	
<b>Recur Frequency</b>	
<b>Status</b>	Completed
<b>Notes</b>	Evaluate and complete interim reclamation on recent flowline maintenance disturbance. Rip, disk, compost, seed and mulch corridor.  Evaluate and clean up rutting which occurred off lease road, reclaim accordingly.



# Work Completion Report

## Photos

---

<b>Photo Type</b>	General
<b>Photo Name</b>	P1
<b>Photo Notes</b>	
<b>PhotoBlobID</b>	



<b>Photo Type</b>	General
<b>Photo Name</b>	P2
<b>Photo Notes</b>	
<b>PhotoBlobID</b>	



**Work Completion Report**



Photo Type	General
Photo Name	P3
Photo Notes	
PhotoBlobID	





**Work Completion Report**



<b>Photo Type</b>	General
<b>Photo Name</b>	DR1
<b>Photo Notes</b>	
<b>PhotoBlobID</b>	



**Work Completion Report**







## Work Completion Report

<b>Photo Type</b>	General
<b>Photo Name</b>	DR2
<b>Photo Notes</b>	
<b>PhotoBlobID</b>	



**Work Completion Report**





## Work Completion Report

<b>Photo Type</b>	General
<b>Photo Name</b>	DR3
<b>Photo Notes</b>	
<b>PhotoBlobID</b>	



## Work Completion Report





## Work Completion Report

<b>Photo Type</b>	General
<b>Photo Name</b>	DR4
<b>Photo Notes</b>	
<b>PhotoBlobID</b>	



**Work Completion Report**







## Work Completion Report

<b>Photo Type</b>	General
<b>Photo Name</b>	SC1
<b>Photo Notes</b>	
<b>PhotoBlobID</b>	



**Work Completion Report**





## Work Completion Report

<b>Photo Type</b>	General
<b>Photo Name</b>	SC2
<b>Photo Notes</b>	
<b>PhotoBlobID</b>	



## Work Completion Report





## Work Completion Report

<b>Photo Type</b>	General
<b>Photo Name</b>	SC3
<b>Photo Notes</b>	
<b>PhotoBlobID</b>	



## Work Completion Report







## Work Completion Report

<b>Photo Type</b>	General
<b>Photo Name</b>	SC4
<b>Photo Notes</b>	
<b>PhotoBlobID</b>	



**Work Completion Report**





## Work Completion Report

**Photo Type**

Post-Completion

**Photo Name**

Post-Completion

**Photo Notes**

**PhotoBlobID**



## Work Completion Report





**Work Completion Report**

**Photo Type** Pre-Completion

**Photo Name** Pre-Completion

**Photo Notes**

**PhotoBlobID**



**Photo Type** Red Zone

**Photo Name** Red Zone

**Photo Notes**

**PhotoBlobID**





## Work Completion Report

OXY		OCCIDENTAL GROUND DISTURBANCE & PIPELINE CONSTRUCTION RED ZONE CHECK LIST		OXY	
LOCATION:		Greenmyer 35C-3H2		DATE: 5/25/23	
PROJECT ENGINEER:				1-CALL REQUEST#: A313801708	
OCCIDENTAL REP:		Drew Stormo		PHONE#: 303 913 7407	
EXCAVATOR REP:		Toby Clark, Ely Pomayrac, Justin Kato, Michael Borch		PHONE#: 303 523 8237 710-518-7781	
This form is to be used in conjunction with OXY Tailgate Safety Meeting & Excavation Inspection Forms.					
OXY REP	BEFORE ANY EXCAVATION IS STARTED THAT DAY:				EXC REP
✓	Verify ALL known lines/wires within 100' of right-of-way (ROW) have been flagged by the operator of the utility or their designee. <i>KPK, KRM, EL &amp; Electric, Xcel</i>				✓
✓	Verify that GIS Portal and other sources of information have been reviewed by OXY and Contractor personnel.				✓
✓	Identify and overhead hazards and take appropriate steps to manage them. Use a spotter, wire sleeve, or other methods as necessary. <i>Now in Work Area</i>				✓
✓	If survey stakes are "down", the ROW must be re-staked prior to excavation. If the locate markings are down, the excavator must request a "refresh" with One-Call. The "refresh" must NOT be done by an OXY employee or designee, but by the original marking organization.				✓
✓	Verify that the contractor has walked the ditch line in front of the excavator (prior to excavation) to verify all locate markings are accounted for. If available, a locator should assist the contractor.				✓
✓	Verify the One-Call Locate Request documents are furnished by the Contractor and have been reviewed by OXY and Contractor personnel. <i>5/22/23 - Call Xcel, Ray</i>				✓
✓	Verify the One-Call Locate Request is current (more than 48 hours and less than <del>25</del> <sup>30</sup> days old) for the section of ROW that will be excavated. This needs to be documented with copies. <i>5/22/23</i>				✓
✓	Check that the excavating equipment operator has been properly trained and is qualified to operate the equipment.				✓
✓	Verify the excavating employees are experienced, have adequate equipment and PPE.				✓
OXY REP	VERIFY ALL EXISTING UTILITIES HAVE BEEN MARKED:				EXC REP
✓	Check fences and fields for <u>markers</u> signs, <u>valves</u> stub-outs, etc. <i>Markers along Road, Valves to NW</i>				✓
✓	Drive the perimeter of the day's excavation area. Verify road crossings and lines to be crossed.				✓
✓	Noting surface encumbrances such as <u>tank batteries</u> , <u>wells</u> , valves, phone pedestals, <u>electrical</u> <u>junction boxes</u> or other signs of underground utilities.				✓
✓	Noting any evidence of previous excavations along the ROW. <i>Gas lift up marks</i>				✓
✓	Verify ALL lines/wires running parallel with the ROW are flagged (within 50' of center line).				✓
N/A	Exposing ALL lines/wires being crossed via vacuum excavation (hydro-vac or air-vac) if possible. Dispose of the mud properly. <i>disk over lines only</i>				N/A
✓	Verify that landowner (if any) has been contacted and has identified all known private utilities in the area.				✓
✓	Draw a sketch or take a picture of the excavation area showing markers or exposed underground utilities.				✓
✓	If possible, have all power in the area of the excavation de-energized prior to any excavation. If it is not possible, make sure the excavator is aware of the hazard.				✓





## Work Completion Report

---

**Photo Type**

Seed Mix

**Photo Name**

Seed Mix

**Photo Notes**

**PhotoBlobID**



## Work Completion Report

Granite Seed -  
Denver

From:  
490 East 76th Ave.,  
Unit A  
Denver, CO 80229

1 of 1

Mix Name: **Custom Mix**

**3-64591**

Mix #: **238772**

**Dryland Maintenance - GRENNMYER 35C-  
3HZ, WAGNER 34**

% Pure	Common Name	Variety	G + D or H	Origin
14.89	SWITCHGRASS	Dacotah	96 + 9 = 95	MN
14.58	WILDRYE, DAHLURIAN	VNS	91 + 4 = 95	ND
12.22	INTERMEDIATE WHEATGRASS	Manifest	85 + 0 = 85	CAN
11.05	PUBESCENT WHEATGRASS	Maniska	94 + 0 = 94	MT
10.71	BROMEGRASS, SMOOTH	Manchar	97 + 0 = 97	IO
10.49	RYEGRASS, PERENNIAL	Oro Verde (F)	99 + 0 = 99	OR
6.31	BLUESTEM, LITTLE	Aldous	84 + 12 = 96	KS
5.71	SIDEOTS GRAMA	Bulte	92 + 0 = 92	MN
4.51	BLUE GRAMA	Lovington	92 + 4 = 96	NM
1.75	BUFFALOGRASS	Texoka Trt	96 + 3 = 99	TX

0.54 Other Crop

Date Tested: 14-Jun-22

7.22 Inert Matter

Hard Seed: 3.46

0.03 Weed Seed

Noxious Weed: NONE FOUND

Net Weight: 31.50 Lbs. PLS 36.39 Lbs. Bulk

Coverage: 2.100 Acre

#### NOTICE TO BUYER LIMITATIONS OF WARRANTIES AND REMEDIES

Buyer acknowledges that the seed is sold "as is" and that the seed is not warranted to be of any particular quality or quantity. The labeled seller warrants that all seed sold has been tested and found to be of the highest quality and that the seed conforms to the label description, within recognized tolerances. THIS WARRANTY IS IN LIEU OF ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, INCLUDING WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. THERE ARE NO WARRANTIES WHICH EXTEND BEYOND THE DESCRIPTION ON THE LABEL.

No claim shall be asserted against the labeled seller unless Buyer reports to the labeled seller within a reasonable period after discovery (not to exceed thirty days). Any condition that might lead to a complaint. BUYER'S EXCLUSIVE REMEDY FOR ANY CLAIM OR LOSS RESULTING FROM BREACH OF WARRANTY, BREACH OF CONTRACT OR NEGLIGENCE (INCLUDING BUT NOT LIMITED TO INCIDENTAL OR CONSEQUENTIAL DAMAGES) SHALL BE LIMITED TO REPAYMENT OF THE PURCHASE PRICE.

By acceptance of the seed, Buyer agrees the terms and conditions stated above are a benefit to the bargain and constitute the entire agreement between Buyer and the labeled seller. Buyer shall return the original unopened seed package to the labeled seller within twenty days of receipt for a refund of the purchase price if not accepted under these terms.

#### NOTICE: REQUIRED ARBITRATION / CONCILIATION / MEDIATION

The seed laws of several states including Arkansas, California, Colorado, Florida, Georgia, Idaho, Illinois, Indiana, Minnesota, Mississippi, Montana, North Dakota, South Carolina (Section 46-21-260), South Dakota, Texas and Washington require arbitration, conciliation or mediation of disputes involving alleged defective seed before certain legal actions may be maintained against a seller. North Carolina offers an alternative to court action that allows claims to be investigated and heard before the Special Seed Board. A complaint (per form for AR, CO, FL, IL, IN, MN, MS, MT, NC, SC, TX, WA, signed only, CA, GA, ID, ND, SD) must be filed with the Department of Agriculture or Seed Commissioner (IN) or State Plant Board (AR) or Commissioner of Agriculture (NC) within such time as to permit an inspection of seed, crops or plants (by an Arbitration Committee - AR, ID, MS, SC). In NC, failure to follow this procedure will limit the amount of damages recoverable. Certified copy of complaint must be sent by registered mail to the labeled seller as provided in individual state law. Information about these requirements may be obtained from the state Department of Agriculture.

Will Call:  
Norther Colorado Constructors - NCC



# Work Completion Report

Photo Type	Site Map
Photo Name	Site Map
Photo Notes	
PhotoBlobID	

