

Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad

Location # 335160



Jun 7, 2023 at 10:03:14 AM
CO



Jun 7, 2023 at 10:03:22 AM
CO

Photo # 9701 From entrance to location

Photo # 9702 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad

Location # 335160



Photo # 9703 Location

Photo # 9704 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad

Location # 335160



Photo # 9705 Location



Photo # 9706 Stained soils & gravel

Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad

Location # 335160



Photo # 9707 Stained soils & gravel



Photo # 9708 Stained soils & gravel

Inspection Photos
Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad
Location # 335160



Photo # 9710 Wellhead cellar lacks wildlife egress



Photo # 9711 Meter calibration info not conspicuously posted

Inspection Photos
Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad
Location # 335160



Jun 7, 2023 at 10:10:25 AM
CO



Jun 7, 2023 at 10:10:34 AM
CO

Photo # 9712 Meter calibration info not conspicuously posted

Photo # 9713 Meter calibration info not conspicuously posted

Inspection Photos
Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad
Location # 335160



Photo # 9714 Meter calibration info not conspicuously posted