

**Operator: 8 NORTH LLC**

**Location Name: FABRIZIUS-611N61W 33SESW**

**Loc ID: 302848**

**Inspection: 696304945**



**Exhibit A**



**Exhibit B**



**Exhibit C**

**CA:** Stained Soil at Wellhead, Exhaust and Gas Engine; For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

**CA Resolution:** Identified stained soil at Wellhead, Exhaust, and Gas Engine has been properly addressed. Operator has disposed of stained soil and replaced it with fresh soil to comply with Rule 905.e.