

# Inspection Photos

API: 055-06190

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/6/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the location. The road travels thru the center of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/6/2023

## Inspection Photos



**Photo 2.** Facing northwest toward the location. The cut slope of the location is visible along the right side of photo and a run-on ditch. This area shown in right portion of the photo is not stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/6/2023

## Inspection Photos



**Photo 3.** Facing north toward the location. The cut slope of the location is visible and has not sufficiently established vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/6/2023

## Inspection Photos



**Photo 3.** Facing southeast at the location. The surface owner is using the location for a debris burn pit. Red arrow points to pipe riser that remains and is shown in the next photo.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/6/2023

## Inspection Photos



**Photo 5.** There is a pipe riser that remains at the surface of the location that needs to be properly abandoned.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/6/2023

## Inspection Photos



**Photo 6.** There appears to be liner debris at the surface at the southwest side of the pad.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/6/2023

## Inspection Photos



**Photo 7.** There are noxious weeds at the location which include Cheat grass, Red stem filaree, Field bind weed, and Jointed Goat grass. There was much less noxious weeds observed since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/6/2023