

**Operator: HIGHPOINT OPERATING CORPORATION**

**Location Name: RANDALL CREEK 29 SE**

**Loc ID: 444078**

**Inspection: 696304927**



**Exhibit A**



**Exhibit B**



**Exhibit C**



**Exhibit D**

**CA:** All 3 Day Tank Containments are missing or have Wildlife Netting in disrepair and Oily waste. Install or repair wildlife protection equipment. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

**CA Resolution:** Identified stained soil has been properly addressed. Operator has disposed of stained soil and replaced it with fresh soil to comply with Rule 905.e. The Operator has also appropriately replaced and installed new Wildlife Netting to comply with Rule 902.b.