

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NWNE

Location ID: 311549



Photo #286 From entrance to location.



Photo #287 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NWNE

Location ID: 311549



Photo #289 Meter calibration cards not conspicuously posted.



Photo #290 Meter calibration cards not conspicuously posted.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NWNE

Location ID: 311549



Photo #291 Unused equipment.